

FORD:

2015 F-150

ISSUE

Some 2015 F-150 SuperCab and SuperCrew Cab vehicles built on or before 3/25/2015 may exhibit inoperative door latches during or after freezing temperatures.

ACTION

Follow the Service Procedure steps to correct this condition.

SERVICE PROCEDURE

1. Remove all the interior door panels. Refer to Workshop Manual (WSM), Section 501-05.
 - a. On all doors, verify the latch release cable is properly seated and the cable end is properly installed on to the outer handle. (Figure 1)




Figure 1 - Article 15-0052

- b. If improper installation is found, the cable can become kinked and the cable should be replaced. Refer to WSM, Section 501-14.
2. Remove all the center door latch assemblies. Refer to WSM, Section 501-14. Refer to WSM, Section 501-14.
 - a. If equipped with SuperCab rear doors, also remove the lower door latch assemblies.
3. Use compressed air to blow dry all the center door latch assemblies after removal.
4. Use compressed air to blow dry all handle assemblies.
5. If the vehicle is a SuperCab, install new rear door lower latch assemblies. Refer to WSM, Section 501-14.
6. Use Motorcraft® Multi-Purpose Grease or equivalent to lubricate the steel cable and all moving components of the center latch assemblies.
 - a. Use Motorcraft® Multi-Purpose Grease or equivalent and lubricate the driver's latch lock rod and all attachment points.
7. Use Motorcraft® Multi-Purpose Grease or equivalent and spray the inside of all front and rear door exterior handles.
 - a. Lubricate the steel cable and all moving exterior handle components while cycling the handle.

NOTE: The information contained in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.

8. Reinstall all center door latch assemblies. Refer to WSM, Section 501-14.
9. Reinstall all the interior door panels. Refer to WSM, Section 501-05.

PART NUMBER	PART NAME
FL3Z-15221A01-A	Cable - Left Front Outer Door Handle To Latch Cable
FL3Z-15221A00-A	Cable - Right Front Outer Door Handle To Latch Cable
FL3Z-16266A46-B	Cable - Left Rear Outer Door Handle To Latch Cable
FL3Z-16266A46-A	Cable - Right Rear Outer Door Handle To Latch Cable
FL3Z-18264A01-B	Latch - Left Rear - SuperCab
FL3Z-18264A00-B	Latch - Right Rear - SuperCab
XL-5-A	Motorcraft® Multi-Purpose Grease

OPERATION	DESCRIPTION	TIME
150052A	2015 F-150 SuperCab: Remove Door Latches On All Four (4) Doors, Inspect Cable Routing, Replace Cable(s) As Necessary One (1) Or More Doors, Clean, Lubricate Or Replace Latches On One (1) Or More Doors Following The Service Procedure (Do Not Use With Any Other Labor Operations)	3.9 Hrs.
150052A	2015 F-150 SuperCrew Cab: Remove Door Latches On All Four (4) Doors, Inspect Cable Routing, Replace Cable(s) As Necessary One (1) Or More Doors, Clean, Lubricate Or Replace Latches On One (1) Or More Doors Following The Service Procedure (Do Not Use With Any Other Labor Operations)	4.0 Hrs.

WARRANTY STATUS:

Eligible Under Provisions Of New Vehicle Limited Warranty Coverage

Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB. Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

DEALER CODING

BASIC PART NO.	CONDITION CODE
18264A00	41