

**ANALOG SPEEDOMETER NEEDLE STICKING AND/OR INCORRECT
SPEED INDICATION - BUILT ON OR BEFORE 8/31/2015****TSB 15-0193****FORD:**

2015 F-150

ISSUE

Some 2015 F-150 vehicles built on or before 8/31/2015 may exhibit an analog speedometer needle that sticks and/or indicates a vehicle speed while the vehicle is in park.

ACTION

Follow the Service Procedure steps to correct the condition.

SERVICE PROCEDURE

1. Does the digital speedometer within the information display read correctly?
 - a. Yes - proceed to Step 2.
 - b. No - this article does not apply. Refer to the Workshop Manual (WSM), Section 413-01 for normal diagnostics.
2. Replace the instrument panel cluster (IPC). Refer to the WSM, Section 413-01.

PART NUMBER	PART NAME
10849	Instrument Panel Cluster - See Parts Catalog For Specific Application

OPERATION	DESCRIPTION	TIME
150193A	2015 F-150: Inspect And Replace The IPC (Do Not Use With Any Other Labor Operations)	0.5 Hr.

WARRANTY STATUS:

Eligible Under Provisions Of New Vehicle Limited Warranty Coverage

Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB. Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

DEALER CODING

BASIC PART NO.	CONDITION CODE
10849	42

NOTE: The information contained in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.