

DRLs test sheet						
	Module	Address	Values	Values	Values	Notes
Disbale Candian DRL's as Per Google docs tested on American trucks	BCM	726-16-02	0101	0101	0049	DRL Cluster Control 1 enabled
	BCM	726-21-01	xxxx	xxxx	x1xx	Make this change when disabling Canadian forced DRLs to cluster enabled
	BCM	726-27-01	xxxx	xxx0	xxxx	Ability to do Fogs and High beams at same time
	BCM	726-50-01	108E			
	IPC	720-02-01	xxEx	xxxx	xxxx	DRL light option present in productivity screen
Result = DRLs disabled, option present in productivity screen, option in productivity screen fails to enable DRLs when selected						
Livinitup	BCM	726-21-01	1401	0201	0168	
Stock config of Red 2015 Canada lariat with halogen headlamps	BCM	726-16-02	0202	0202	024F	Stock config
	BCM	726-21-01	1401	0201	0269	Stock config
	BCM	726-27-01	0100	0000	0056	Ability to do fogs and high beams at same time
	BCM	726-50-01	0280			Stock config
	IPC	720-02-01	4D80	3C51	3CC0	Stock config
Result = Halogen DRLs enabled, DRL light option missing from productivity screen						
Stock config of Blue 2015 Canada lariat with LED headlamps	BCM	726-16-02	0202	0202	024F	Stock config
	BCM	726-21-01	1401	0201	0269	Stock config
	BCM	726-27-01	0001	0001	0057	Stock config
	BCM	726-50-01	108E			Stock config
	IPC	720-02-01	?	?	?	Stock config
Result = LED DRLs enabled, DRL light option missing from productivity screen						
My truck, Blue 2016 Lariat, Canadian purchased, LED headlamps, trial A	BCM	726-16-02	0101	0101	0049	
	BCM	726-21-01	1401	0201	0168	
	BCM	726-27-01	0001	0000	0056	
	BCM	726-50-01	108E			
	IPC	720-02-01	4DE0	3C51	1C00	
Result = LED DRLs disabled, option present in productivity screen, option in productivity screen fails to enable DRLs when selected						
My truck, test 1	BCM	726-16-02	0101	0101	0049	
	BCM	726-21-01	1401	0201	0269	
	BCM	726-27-01	0100	0000	0056	
	BCM	726-50-01	108E			
	IPC	720-02-01	4DE0	3C51	1C00	
Result = LED DRLs disabled, option present in productivity screen, option in productivity screen fails to enable DRLs when selected						
My truck, test 2	BCM	726-16-02	0202	0202	024F	
	BCM	726-21-01	1401	0201	0269	
	BCM	726-27-01	0100	0000	0056	
	BCM	726-50-01	108E			
	IPC	720-02-01	4DE0	3C51	1C00	
Result = LED DRLs disabled, option present in productivity screen, option in productivity screen fails to enable DRLs when selected						
My truck, test 3	BCM	726-16-02	0202	0202	024F	
	BCM	726-21-01	1401	0201	0168	
	BCM	726-27-01	0100	0000	0056	
	BCM	726-50-01	108E			
	IPC	720-02-01	4DE0	3C51	1C00	
Result = LED DRLs disabled, option present in productivity screen, option in productivity screen fails to enable DRLs when selected						
My truck, test 4	BCM	726-16-02	0202	0202	024F	
	BCM	726-21-01	1401	0201	0168	
	BCM	726-27-01	0100	0000	0056	
	BCM	726-50-01	108E			
	IPC	720-02-01	4DE0	3C51	1C00	
Result = DRLs are back! -- but once switched off in productivity screen they won't ever enable again even with a full ignition cycle.						
My truck, test 5	BCM	726-16-02	0202	0202	024F	Stock Config
	BCM	726-21-01	1401	0201	0269	Stock Config
	BCM	726-27-01	0100	0000	0056	Stock Config
	BCM	726-50-01	108E			Stock Config
	IPC	720-02-01	4D80	3C51	1CA0	Stock Config
Result = DRLs are back!						

