



It's my first day!



I realize 2014 is 12th Gen, but Limited Trim had MFT

In 2017 Ford changed the physical size of the USB hub. USB-C hub retrofit requires bracket GC3T-14G332-AA or similar.

Don't waste money to retrofit Sync 3 hardware as of 2021. Instead, retrofit Sync 4. If you decided to install old Sync 3 parts then proceed.

Some older Non-Nav APIM's may not have enough memory for this

Force install invalid APIM firmware. For advanced users only! High risk of failure! Not recommended!

Enable:
7D0-02-02 xxxx 9xxx xxxx
7D0-02-03 4xxx
7D0-09-01 xxxx EExx xxxx
7D0-09-02 xxxx xxxx 21xx