

JOB# 1 CHARGES-----

LABOR-----

1 72FOZ DIAGNOSE TRIM TECH(S):225 75.00

INSTALL WHEEL WELL LINERS IN BACK SEAT

INSTALLED LINERS AS REQUESTED

JOB# 1 TOTALS-----

LABOR 75.00

JOB# 2 CHARGES-----

JOB# 1 JOURNAL PREFIX FOCS JOB# 1 TOTAL 75.00

LABOR-----

2 63FOZ-13E03 PCM REFLASH TECH(S):225 WARRANTY

Added Operation (BROOKSW @ 07/31/2013 07:58)

CERTAIN 2013 MODEL YEAR F-150 VEHICLE BUILT WITH 3.5L GTDI

ENGINE MAY HAVE A PORTION OF THE EMISSIONS SYSTEM CAUSING

A BIASED RICH CONDITION.

THIS CONDITION MAY CAUSE MORE FUEL USE AND A NEGATIVE EFFECT

ON THE EMISSIONS. THE PCM NEEDS TO BE REFLASHED TO CORRECT

THIS CONDITION.

REFLASHED PCM AS PER RECALL

JOB# 2 TOTALS-----

JOB# 2 JOURNAL PREFIX FOCS JOB# 2 TOTAL 0.00

ESTIMATE-----

CUSTOMER HEREBY ACKNOWLEDGES RECEIVING

ORIGINAL ESTIMATE OF \$75.00 (+TAX)

MO. 33

Thank you for giving Cal Worthington Ford the opportunity to service your vehicle. In the near future, you may receive a Service Survey from Ford National Headquarters regarding today's service. If you cannot answer "Completely Satisfied" please let us know. This is our dealership's report card and your input is extremely important to us.

Service Appointment
And Special Discounts
Now Available On Line At
www.calworthington.com

