

**KING RANCH/PLATINUM/LARIAT - DRIVER'S SEAT CUSHION COVER  
LOOSE OR WRINKLED MATERIAL****TSB 15-0147****FORD:**

2015 F-150

**ISSUE**

Some 2015 F-150 King Ranch, Platinum and Lariat vehicles may exhibit loose or wrinkled material in the center of the driver's seat cushion cover.

**ACTION**

Follow the Service Procedure steps to correct the condition.

**SERVICE PROCEDURE**

1. Does the driver seat exhibit loose or wrinkled material in the center of the seat cushion cover?
  - a. Yes - proceed to Step 2.
  - b. No - this article does not apply. Refer to the Workshop Manual (WSM), Section 501-10 for normal diagnosis.
2. Replace the driver's seat cushion cover. Refer to the WSM, Section 501-10.

PART NUMBER	PART NAME
FL3Z-1662901-AD	Lariat Gray Cover
FL3Z-1662901-AE	Lariat Ebony Cover
FL3Z-1662901-AF	Lariat Camel Cover
FL3Z-1662901-BB	King Ranch Mesa
FL3Z-1662901-CC	Platinum Brunello
FL3Z-1662901-CD	Platinum Ebony

OPERATION	DESCRIPTION	TIME
150147A	2015 F-150 King Ranch, Platinum And Lariat: Inspect And Replace The Drivers Seat Cushion Cover (Do Not Use With Any Other Labor Operations)	1.2 Hrs.

**WARRANTY STATUS:**

Eligible Under Provisions Of New Vehicle Limited Warranty Coverage

Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB. Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

**DEALER CODING**

BASIC PART NO.	CONDITION CODE
1662901	34

NOTE: The information contained in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.