

Recalls



2016 Ford F-150

We found the following field service action listed on your vehicle.

VIN:1FTEW1EGXGFB01666

Last updated 09/21/2017



Recall Date: AUG 28, 2017

Recall Title: LEFT HAND REAR SEATBELT BUCKLE INSPECTION

NHTSA Recall Number: AWAITING#

Ford Recall Number: 17C12

Recall Description: REAR INFLATABLE SEATBELT BUCKLE SOME RIVETS USED TO ATTACH THE INFLATABLE SEAT BELT BUCKLE ASSEMBLY ON THE LEFT REAR SEAT TO ITS MOUNTING BRACKET MAY HAVE INADEQUATE RIVET HEAD THICKNESS.A SEAT BELT BUCKLE ASSEMBLY WITH AN INADEQUATE RIVET MAY FAIL TO COMPLY WITH SECTION 5.2 OF FMVSS 210.

Risk to Safety: INADEQUATE RIVET HEAD THICKNESS MAY ALLOW SEPARATION OF THE LEFT REAR INFLATABLE SEAT BELT BUCKLE FROM ITS MOUNTING BRACKET DURING A CRASH,INCREASING THE RISK OF INJURY.

Remedy Program: OWNERS WILL BE NOTIFIED BY MAIL AND INSTRUCTED TO TAKE THEIR VEHICLE TO A FORD OR LINCOLN DEALER TO HAVE THE LEFT REAR SEAT BELT BUCKLE ASSEMBLY RIVET HEAD THICKNESS INSPECTED.THE SEAT BELT BUCKLE ASSEMBLY WILL BE REPLACED IF THE RIVET IS FOUND TO BE INADEQUATE.THERE WILL BE NO CHARGE FOR THIS SERVICE.FORD IS EXCLUDING REIMBURSEMENT FOR COSTS BECAUSE THE ORIGINAL WARRANTY PROGRAM WOULD PROVIDE FOR A FREE REPAIR FOR THIS CONCERN.FORD WILL FORWARD A COPY OF THE NOTIFICATION LETTERS TO DEALERS TO THE AGENCY WHEN AVAILABLE.

Status: 12 - RECALL INCOMPLETE. REMEDY NOT YET AVAILABLE.

Manufacturer Notes: TO CHECK FOR NON-SAFETY-RELATED PROGRAMS APPLICABLE TO YOUR VEHICLE, SEE [HTTP://WWW.FORD.COM/](http://www.ford.com/) OR CALL YOUR FORD DEALER.

Be advised that this system tracks Recalls and Customer Satisfaction Programs for which vehicles are subject to repair in the United States. The information provided is subject to change and update. There may be temporary delays in update of information on this site due to a number of factors. For the latest information regarding the status of your vehicle or any recall program of Ford Motor Company, please contact your local dealership directly or the Customer Relationship Center.

A recall is an action by the Company to remedy a safety concern related to a vehicle defect or regulatory requirement. It may require that you return your vehicle to the dealer for service. If your vehicle is not affected, it may be because it was built at a different time or using a different part than the affected vehicles.

[DISCLOSURES](#) 