TSB 12-10-19 (Continued)

N	0	T	Е

PLEASE ADVISE THE CUSTOMER THAT THIS VEHICLE IS EQUIPPED WITH AN ADAPTIVE TRANSMISSION SHIFT STRATEGY WHICH ALLOWS THE VEHICLE'S COMPUTER TO LEARN THE TRANSMISSION'S UNIQUE PARAMETERS AND IMPROVE SHIFT QUALITY, WHEN THE ADAPTIVE STRATEGY IS RESET. THE COMPUTER WILL BEGIN A RE-LEARNING PROCESS. THIS RE-LEARNING PROCESS MAY RESULT IN FIRMER THAN NORMAL UPSHIFTS AND DOWNSHIFTS FOR SEVERAL DAYS.

PART NUMBER	PART NAME
BL3Z-5E212-E	Catalytic Converter Assembly
W520514-S440	Nuts (2 Reg)
CL3Z-19E672-A	Deflector Plate
BL3Z- 6K775-B	CAC
W711281-S300	Push Pin (2 Reg)

WARRANTY STATUS: Eligible Under Provisions Of

New Vehicle Limited Warranty Coverage And **Emissions Warranty**

Coverage

Warranty/ESP coverage limits/policies/prior approvals are not altered by a TSB. Warranty/ESP coverage limits are determined by the identified causal part and verified using the OASIS

TIME

0.8 Hr.

part coverage tool.

OPERATION 121019A

DESCRIPTION

2011-2012 F-150 3.5L

GTDI: Check DTCs, Replace CAC Assembly. Includes Time To Transfer Or Install New CAC Shield (Do Not Use With Any Other Labor Operations)

121019B 2011-2012 F-150 3.5L 1.2 Hr. GTDI: Check DTCs, Replace The Left Catalytic Converter, Replace CAC Assembly, Includes Time To Transfer Or Install New CAC Shield (Do Not Use With Any Other Labor

Operations)

121019C 2011-2012 F-150 3.5L 0.9 Hr.

GTDI: Check DTCs. Replace CAC Assembly, Includes Time To Transfer Or Install New CAC Shield. And Reprogram The PCM (Do Not Use With Any Other Labor Operations)

121019D 2011-2012 F-150 3.5L 1.4 Hrs.

> GTDI: Check DTCs, Replace The Left Catalytic Converter, Replace CAC Assembly, Includes Time To Transfer Or Install New

CAC Shield, And

Reprogram The PCM (Do Not Use With Any Other

Labor Operations)

DEALER CODING

CONDITION BASIC PART NO. CODE 5E212 (OPERATION B AND D) 12 6K775 (OPERATION A AND C) 42